BRUHAT BANGALORE MAHANAGARA PALIKE

INSPECTION REPORT

Division: Hebbal	Sub Division: Hebbal / JC Nagar
Ward No. 18	

No.	Descriptions	Details	Rema
1	Name of the work	Constructino of drain and culverts in Naidu Layout in Ward No. 18	
2	Administrative Sanction No and Date	EE(H)AS/PR/97/13-14 dated: 30/10/2013	
3	Technical Sanction No and Date	EE(H)TS/102/13-14 dated: 30/10/2013	
4	Job Number, date and P-code	018-14-000004	
5	Estimate Cost (Rs in Lakhs)	Rs. 10.00 Lakhs	
6	Tender (or) Direct Entrustment to KRIDL	Tender	
7	If tendered, Tender notification number date and publication in Daily news paper	EE/H/TEND/09/13-14 dated:	
8	Tender Approval Details	Rs. 858008.93	
9	Date of work order and number	EE/H/AE/WO/179/13-14 dated: 10/02/2014	
10	Stipulated time and completion	9/4/2014	
11	Actual date of completion	30/04/2014	
12	Delay if any	Penalty imposed.	
13	Reasons for delay		
14	Payment made till date	Payment due	
15	Pending bill details status of work	Completed	
16	Quality test report	Sumitted	
17	Photographs of the completed works	Submitted	
18	M.B No and page number	771/11-12 P-7072-76	
19	Bill form	Submitted	
20	Remarks: Recommendations of the inspection team Name / Mobile No / E-Mail	certified that the above wor is inspected on 09-03-2016, v mg ed bill file which are te Charge. work is satisfactor Bill payment may be relea	

ಸಹಾಯಕ ಅಭಿಯಂತರರು

Constn. of drain and culverts in Naidu Layout in ward No. 181

G. R. Hiremath EE Retd)
District Quality Monitor
Bruhat Bangalore Ma